

2/8

FIG. 2





FIG. 3



SUBSTITUTE SHEET (RULE 26)

3/8

FIG. 4







FIG. 5




**SUBSTITUTE SHEET (RULE 26)** 






**SUBSTITUTE SHEET (RULE 26)** 



SUBSTITUTE SHEET (RULE 26)

FIG. 9







FIG. 11

	Plate 1	Plate 2	Plate 3	Mean
neg control TA98	20	23	30	24
without charcoal treatment	105	100	113	106
with charcoal treatment	23	26	24	24

neg	24
without charcoal treatment	106
with charcoal treatment	24



without S9